



Электромашинный
преобразователь частоты
серии ПСЧ.

Тип	Размеры, мм										
	l	l10	l12	l32	l34	l36	l80	l87	l92	b1	b12
ПСЧ-12	265	520	150	225	140	335	1030	395	150	355	110
ПСЧ-15	265	420	150	195	90	335	870	345	125	355	110
ПСЧ-30	265	520	150	225	140	335	1030	395	150	355	110
ПСЧ-50	345	560	200	280	180	345	1185	515	220	355	130
ПСЧ-50КЧ	325	560	150	272	185	384	1185	450	150	440	120
ПСЧ-60	325	560	150	272	185	384	1185	450	150	440	120
ПСЧ-100	400	854	225	180	295	440	1560	x	170	440	170
Тип	Размеры, мм										
	b30	b31	b32	b34	h	h10	h12	h31	h34	h35	h36
ПСЧ-12	440	390	550	80	225	25	25	620	280	535	420
ПСЧ-15	440	390	550	80	225	25	25	620	280	535	420
ПСЧ-30	440	390	550	80	225	25	25	620	280	535	420
ПСЧ-50	440	520	595	120	315	28	28	820	535	620	575
ПСЧ-50КЧ	560	520	595	120	315	28	28	820	535	620	570
ПСЧ-60	560	520	595	120	315	28	28	820	535	620	570
ПСЧ-100	560	x	720	170	335	22	22	840	490	715	670